



Front View



■ Loose/broken/delaminated
■ Damage/wear/hole

■ Previous repair
■ Replaced piece


Rear View



■ Missing
■ Spindles not original to desk

■ Add-ons
■ Inscriptions

Right Side




Red square: Loose/broken/delaminated

Orange square: Damage/wear/hole

Blue square: Previous repair

Green square: Replaced piece

Left Side




Brown square: Missing

Pink square: Spindles not original to desk

Yellow square: Add-ons

Purple square: Inscriptions

Top




Loose/broken/delaminated
 Damage/wear/hole

Previous repair
 Replaced piece

Missing
 Spindles not original to desk

Add-ons
 Inscriptions


Bottom



■ Loose/broken/delaminated
■ Damage/wear/hole

■ Previous repair
■ Replaced piece

Bottom




■ Missing
■ Spindles not original to desk

■ Add-ons
■ Inscriptions

Drawer Front, Outer Surface



Rear Surface of Drawer Front



■ Loose/broken/delaminated
■ Damage/wear/hole



■ Previous repair
■ Replaced piece

■ Missing
■ Spindles not original to desk

■ Add-ons
■ Inscriptions

Inside Surface of Left Drawer Side

Inside Surface of Right Drawer Side



■ Loose/broken/delaminated

■ Damage/wear/hole

■ Previous repair

■ Replaced piece

■ Missing



■ Spindles not original to desk

■ Add-ons

■ Inscriptions

Rear Surface of Drawer Back

Front Surface of Drawer Back




■ Loose/broken/delaminated
■ Damage/wear/hole

■ Previous repair
■ Replaced piece

■ Missing
■ Spindles not original to desk

■ Add-ons
■ Inscriptions


Upper Surface of Drawer Bottom



Loose/broken/delaminated
Damage/wear/hole

Previous repair
Replaced piece

Lower Surface of Drawer Bottom




Missing
Spindles not original to desk

Add-ons
Inscriptions


Outside Surface, Right Drawer Side

Outside Surface, Left Drawer Side




 Loose/broken/delaminated

 Damage/wear/hole


 Previous repair

 Replaced piece

 Missing

 Spindles not original to desk

 Add-ons

 Inscriptions